



Replace troublesome **Learjet** DN-101 or DN-104 gyros in **3 easy steps** with dependable 10,000 Hour Sperry/Honeywell gyros.



Tel: 905-871-0733


Fax: 905-871-5460

Web: www.insightavionics.com

GYRO 4000

STC'd for Learjet: 23, 24, 25, 28, 29, 31, 35 and 55 DN-101, 104 equipped Learjets as a direct replacement.

Installation of Insight's Gyro 4000 now complete.



Insight